LABOR & PARTS		MANUFACTURER S
J# 1 94BMZ-BODY1 BODY 1 TECH(S):5424 CUSTOMER STATES THE CARBON FIBER TRIM AROUND THE SHIFTER WAS NOT INSTALLED WITH OTHER CARBON FIBER PIECES. SOP. INITIAL ENQUIRY CAME IN WITH M. MOYER ON 3/24/2021. D. MITCHELL CONFIRMED KIT CONTENTS 3/29/21 ORDERED TRIM PIECE.	WARRANTY	ADJUSTMENT Federal law require furnish the Nationa Safety Administration bulletins describing
INSTALLED CARBON FIBER CENTER CONSOLE TRIM		vehicles. You may ob
PARTSQTYFP-NUMBERDESCRIPTIONUNIT PRICE- JOB # 1	WARRANTY 0.00	bulletins from other N.H.T.S.A. In addition publications or organization which residents to the control of the
JOB # 1 TOTAL LABOR & PARTS J# 2 01BMZ-MPI MULTIPOINT INSPECT'N TECH(S):5424	0.00	fee or for tree
PERFORM MULTI-POINT INSPECTION PERFORMED MULTI-POINT INSPECTION THANK YOU FOR YOUR BUSINESS!	INTERNAL	LOSS / DAMAGE Under certain circums theft or other cause Mile One may not be
PARTSQTYFP-NUMBERDESCRIPTIONJOB # 2 TOTAL PARTS	0.00	or damage to motor v in the vehicle hous
JOB # 2 TOTAL LABOR & PARTS	0.00	facility. You have a rig representative about
J# 3 01BMZ-SANITIZE COVID-19 SANITIZE TECH(S):5424 WE SANITIZED YOUR INTERIOR SURFACES USING A BMW APPROVED DISINFECTANT, PAYING SPECIAL ATTENTION TO AREAS THAT ARE TOUCHED FREQUENTLY WITH YOUR HANDS (STEERING WHEEL, RADIO BUTTONS, SEAT BELT LATCH, DOOR HANDLES, SHIFT KNOB, ETC.) YOUR VEHICLE'S INTERIOR WAS SANITIZED AGAIN AFTER SERVICE. THANK YOU FOR ALLOWING BMW OF SILVER SPRING TO SERVICE YOUR VEHICLE.	INTERNAL	responsibility, includir insurance coverage repair facility. Mile Or for valuables left in t money, tapes. CDs detectors. CB radios
PARTSQTYFP-NUMBERDESCRIPTIONJOB # 3 TOTAL PARTS	0.00	"Montgomery Cou Limited express wa
JOB # 3 TOTAL LABOR & PARTS	0.00	or 12,000 miles. first. All adjustmen
ESTIMATECUSTOMER HEREBY ACKNOWLEDGES RECEIVING ORIGINAL ESTIMATE OF \$0.00 (+TAX)		performed at the facility as the origin
COMMENTS++LOANER++SOP CARBON FIBER TRIM		

[CONTINUED ON NEXT PAGE] 02:28pm

CUSTOMER COPY

PAGE 1 OF 2

SPECIAL POLICE T PROGRAMS

es manufacture any determine the on certain como ma mizationes ; ni le 2 - - - -

GE DISCLAIMER

vehicle or articles tell sed at a Mile tree ght to ask a Mile crea ut the extent of its and the extent of the ng is not responsible the website inclusions cell phones, and a

unty Req. No. 333 varianty 12 messas whichever come ent work must be same Mile I we