

Fri May 3 10:43:05 2013

AutoZone #4062

2922 GLEN AVE GLENWOOD SPRINGS, CO 81601 (970)384-0177

| CATALOG WARRANTY | PART# | CORE | PRICE |
|-------------------------------------|-------|------|-------|
| Troubleshooting OEM Brand: Volks | | | 0.00 |

P144B

Definition

ááThermostat heater control circuit open
Explanation

ááOpen or short circuit condition

Probable cause

áá1.- Poor electrical connection

áá2.- Failed engine cooling thermostat

Prices and availability are subject to change

THIS IS NOT A RECEIPT