



# Ferrari Los Angeles Service Department

7051 Hayvenhurst Ave., Van Nuys, CA 91406  
T: (818) 464-9111 | F: (818) 464-9103  
service@ferrariLosangeles.com  
www.ferrariLosangeles.com

CAL 000244914 BAR# ARD 279122

INVOICE NUMBER <b>SFCS12937</b>	
CUSTOMER NUMBER <b>23171</b>	
<del>XXXXXXXXXX</del> <del>XXXXXXXXXX</del> <del>XXXXXXXXXX</del> TN <del>XXXX</del>	
RESIDENCE PHONE <del>XXXXXXXXXX</del>	BUSINESS PHONE <del>XXXXXXXXXX</del>
ADVISOR <b>WILLIAM RHODE</b>	TAG NO. <b>202 629</b>
LABOR RATE	MILEAGE <b>24,810</b>
LICENSE NO.	
YEAR / MAKE / MODEL <b>03/FERRARI/360/</b>	
VEHICLE ID NO. <b>ZFFYT53A730133646</b>	
F.T.E. NO.	P.O. NO.
COLOR <b>/</b>	STOCK NO.
COMMENTS	
DELIVERY MILES	SELLING DEALER NO.
R.O. DATE <b>02/13/19</b>	INVOICE DATE <b>02/13/19</b>
REPRINT NUMBER	DELIVERY DATE
<b>MO: 24811</b>	PRODUCTION DATE
<b>I ACKNOWLEDGE NOTICE AND ORAL APPROVAL OF AN INCREASE IN THE ORIGINAL ESTIMATED PRICE.</b> CUST. SIGNATURE <b>X</b> Please issue check payable to "GGM Automotive, LLC".	
<b>NOTICE TO CONSUMER: PLEASE READ IMPORTANT INFORMATION ON BACK.</b>	

JOB# 1 CHARGES-----  
 LABOR-----  
 J# 1 11FEZ ENGINE MINOR TECH(S):224 925.00  
 PERFORM COMPRESSION TEST  
 PERFORMED COMPRESSION TEST.

JOB# 1 TOTALS-----  
 LABOR 925.00

JOB# 1 JOURNAL PREFIX SFCS JOB# 1 TOTAL 925.00

JOB# 2 CHARGES-----  
 LABOR-----  
 J# 2 80FEZ02 USED VEHICLE INSPECT TECH(S):224 525.00  
 PERFORM USED VEHICLE INSPECTION  
 INSPECTION COMPLETED, SEE ATTACHED SHEET

JOB# 2 TOTALS-----  
 LABOR 525.00

JOB# 2 JOURNAL PREFIX SFCS JOB# 2 TOTAL 525.00

ESTIMATE-----  
 CUSTOMER HEREBY ACKNOWLEDGES RECEIVING  
 ORIGINAL ESTIMATE OF \$1450.00 (+TAX)  
 RECOMMENDATIONS-----  
 SEE REPORT CARD

TOTALS-----

THANK YOU FOR YOUR BUSINESS

TOTAL LABOR....	1450.00
TOTAL PARTS....	0.00
TOTAL SUBLET...	0.00
TOTAL G.O.G....	0.00
TOTAL MISC CHG.	0.00
TOTAL MISC DISC	0.00
TOTAL TAX.....	0.00

**TOTAL INVOICE \$ 1450.00**

CUSTOMER SIGNATURE

The Reynolds and Reynolds Company, ERRAIN TITM LE SF6776180 (11/15)

# Quality Vehicle Inspection

Customer Name: ~~XXXXXXXXXX~~

Vehicle Year/Model: 03 FERRARI 360

Date/Time: 02/13/2019 16:38:11

Phone: (H) (424) ~~XXXXXXXXXX~~

VIN: ZFFYT53A730133646

Service Advisor: WILLIAM SHERWOOD RHODE


Technician: MANUEL PEPA

INSPECTION RESULT - OK	WILL REQUIRE FURTHER ATTENTION	REQUIRES IMMEDIATE ATTENTION
------------------------	--------------------------------	------------------------------

Green Yellow Red Serviced

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Due Date: Registration/State Inspection
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check all exterior lights
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Operate and Check Operation
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Wiper/Washer
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Horn
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Warning Lights
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Windows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sunroof
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Outside Mirrors: Inside Mirror Light
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Brake/Turn Signal Lights
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Doors/Locks
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trunk/Hood
<b>Comment</b> HOOD STRUDS SHOCKS COLLAPSED			
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Under Hood---
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Fluid Levels
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Belts
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Battery Connections
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Hoses
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Engine Leaks
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Under Vehicle Check: Before/After---
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Tire Pressure Condition
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Suspension/Steering Components
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Engine/Transmission Mounts
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Exhaust Mounts/Conditions
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Drive Shaft Boots/Joints
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Road Test:
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Starting/Idle
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Acceleration/Braking
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Transmission/Clutch Operations
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Heater/Air Conditioning
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Alignment and Wheel Balance

## Front / Rear Brake Linings

LF	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red		R	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red
LR	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red		R	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red


Inspection Not Taken

**More than 50% remaining**

**20% to 50% remaining**

**Less than 20% remaining**

## Check Tires / Tread Depth


LF	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red		RI	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red
LR	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red		RI	<input checked="" type="checkbox"/> Green	<input type="checkbox"/> Yellow	<input type="checkbox"/> Red

**7/32" or Greater**

**4/32" to 6/32"**

**3/32" or Less**

## Check Battery Performance

  Good  
 Fair  
 Bad

Actual Cold Cranking Amps

Factory Cold Cranking Amps



# Quality Vehicle Inspection

Customer Name: ~~XXXXXXXXXX~~

Vehicle Year/Model: 03 FERRARI 360

Date/Time: 02/13/2019 16:38

Phone: (H) (425) ~~XXXXXXXXXX~~

VIN: ZFFYT53A730133646

Service Advisor: WILLIAM SHERWOOD RHODE

Technician: MANUEL PEPA


INSPECTION RESULT - OK	WILL REQUIRE FURTHER ATTENTION	REQUIRES IMMEDIATE ATTENTION
------------------------	--------------------------------	------------------------------

Green Yellow Red

Serviced

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Due Date: Registration/State Inspection
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Check all exterior lights
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Operate and Check Operation
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Wiper/Washer
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Horn
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Warning Lights
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Windows
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sunroof
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Outside Mirrors: Inside Mirror Light
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Brake/Turn Signal Lights
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Doors/Locks
<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	Trunk/Hood
<b>Comment</b> HOOD STRUDS SHOCKS COLLAPSED			
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Under Hood---
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Fluid Levels
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Belts
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Battery Connections
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Hoses
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Engine Leaks
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Under Vehicle Check: Before/After---
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Tire Pressure Condition
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Suspension/Steering Components
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Engine/Transmission Mounts
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Exhaust Mounts/Conditions
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Drive Shaft Boots/Joints
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	---Road Test:
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Starting/Idle
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Acceleration/Braking
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Transmission/Clutch Operations
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Heater/Air Conditioning
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Alignment and Wheel Balance

### Front / Rear Brake Linings

LF		RF
<input checked="" type="checkbox"/> Green		Green <input checked="" type="checkbox"/>
<input type="checkbox"/> Yellow		Yellow <input type="checkbox"/>
<input type="checkbox"/> Red		Red <input type="checkbox"/>
LR		RR
<input checked="" type="checkbox"/> Green		Green <input checked="" type="checkbox"/>
<input type="checkbox"/> Yellow		Yellow <input type="checkbox"/>
<input type="checkbox"/> Red		Red <input type="checkbox"/>

Inspection Not Taken


<b>More than 50% remaining</b>
<b>20% to 50% remaining</b>
<b>Less than 20% remaining</b>

### Check Tires / Tread Depth

LF		RF
<input checked="" type="checkbox"/> Green		Green <input checked="" type="checkbox"/>
<input type="checkbox"/> Yellow		Yellow <input type="checkbox"/>
<input type="checkbox"/> Red		Red <input type="checkbox"/>
LR		RR
<input checked="" type="checkbox"/> Green		Green <input checked="" type="checkbox"/>
<input type="checkbox"/> Yellow		Yellow <input type="checkbox"/>
<input type="checkbox"/> Red		Red <input type="checkbox"/>

<b>7/32" or Greater</b>
<b>4/32" to 6/32"</b>
<b>3/32" or Less</b>

### Check Battery Performance

	<input checked="" type="checkbox"/> Good
	<input type="checkbox"/> Fair
	<input type="checkbox"/> Bad

Actual Cold Cranking Amps

Factory Cold Cranking Amps

# Quality Vehicle Inspection

Customer Name: ~~XXXXXXXX~~

Vehicle Year/Model: 03 FERRARI 360

Date/Time: 02/13/2019 16:38

Phone: (H) ~~(425) 713-3371~~

VIN: ZFFYT53A730133646

Odometer: 24810

Service Advisor: WILLIAM SHERWOOD RHODE

Technician: MANUEL PEPA

RO: 12937

Tag: 629

INSPECTION RESULT - OK

WILL REQUIRE FURTHER ATTENTION

REQUIRES IMMEDIATE ATTENTION

Green Yellow Red

Service

**General Comment:** BOTH REAR O2 SENSOR PORT MODIFIED.  
VEHICLE HAS AFTER MARKET EXHAUST HEATHER INSTALLED.  
AFTER MARKET STEREO.  
BATTERY BRACKET SUPPORT MISSING.  
ROTORS 13 % WEAR, REMAINING 87 %  
CLUTCH WEAR 49.44 %  
FRONT TIRES 18/12  
REAR TIRES 45/12  
ACID VISIBLE IN THE BATTERY COMPARTMENT.



F131E NOS FERRARI F131E NOS BRUSCONO DIGITEX

INITIALIZED ECU

DISC WEAR ACCUMULATOR

FRONT	13
REAR	13

FRONT	REAR	BOTH
-------	------	------

EXIT





HELP: PUMP (8) - PDM (9)



# INITIALIZED ECU

CLUTCH SV CURRENT CONTROL	0.0	mA
1-2-3 SELECTION SV CONTROL	EV, OFF	
PUMP RELAY CONTROL	OFF	
SELF-CALIBRATED CLOSED CLUTCH POSITION	21.9	mm
DELTA FOR SKIDDING START POSITION (P.I.S...	4.8	mm
CLOSED POTENT. CURRENT AT SYSTEM CE...	909.4	mA
PUMP ACTIVATION COUNTER	64771	
PUMP TIME ON	1644	min
SYSTEM TIME ON	41211	min
CLUTCH OVERHEAT TIME	54	sec
ACTUATOR/GEARBOX CENTERING DELTA	-100	
CLOSED CLUTCH POSITION (NEW CLUTCH)	19.2	mm







HELP: P00P (8) - P00M (9)



### INITIALIZED ECU

GEAR ENGAGEMENTS WITH WRONG SHIFTS	0	
GEARBOX INPUT HIGH RPM	0	
OPPOSITE GEAR ENGAGEMENTS	0	
CLUTCH BEYOND PIS	0	
CLUTCH HYDRAULIC FAILURE	0	
GEAR RELEASE FAILED	0	
MEASUREMENT COUNTER	253	
ENERGY WASTED	0	J
CLUTCH WEAR	48.18	%



PARAMETRI PRINCIPALI



HELP: PAUSE (0) - POWER (0)

INITIALIZED ECU

PAGE 1/2

ENGAGEMENT POTENTIOMETER TRAVEL	531	
SELECTION POTENTIOMETER TRAVEL	538	
CLUTCH PRESSURE PLATE TRAVEL	21.90	mm
CLUTCH PRESSURE PLATE REFERENCE	21.9	mm
HYDRAULIC CIRCUIT PRESSURE	42.7	bar
WATER TEMPERATURE	23.0	°C
BATTERY VOLTAGE	12.8	V
LEVER STATUS	NEUTRAL	
ENGINE RPM	0	rpm
GEARBOX PRIMARY SHAFT RPM	0	rpm
CAR SPEED	0.0	Km/h
REQUESTED GEAR	NEUTRAL	



